



Rev B: 7/15/02
Shortened shaft--removed slipping area.

DRAWING DATE	TOLERANCES EXCEPT AS NOTED
1/20/02	X.X ±.031 X.XX ±.010 X.XXX ±.005 ANGLES ± 1/2°

DYNAMIC SEALING TECHNOLOGIES, INC
9127 DAVENPORT ST NE ~ BLAINE, MN 55449
866-700-DSTI (3784)

CUSTOMER APPROVAL/DATE:

SH MTL/PLTING
CARBON STL
BLK OXIDE

CUSTOMER:
STOCK

THIS DOCUMENT CONTAINS INFORMATION WHICH IS PROPRIETARY TO DYNAMIC SEALING TECHNOLOGIES, INC. (DSTI) NO REPRODUCTION OR PUBLICATION OF THIS DOCUMENT OR IT'S CONTENTS, IN WHOLE OR PART, SHALL BE MADE WITHOUT THE WRITTEN CONSENT FROM DSTI.

HSG MTL/PLTING
CARBON STL
BLK OXIDE

F/N:
120

REV:
B